



ADAPTER FOR DRILL CHUCKS

Weldon shank 19 mm ($^{3}/_{4}$ ") to $^{1}/_{2}$ " x 20 NF

ORDER NO. **ZAP 100**



2. Place drill chuck in direct arbor.



For magnetic core drilling machines with direct arbor 19 mm Weldon (3/4") ProfiSTART MAB 100 **ProfiBASIC** ProfiSPEZIAL AutoMAB 1500

3. Ready for use with twist drill.



GEAR RIM DRILL CHUCK

ORD. NO. INTERNAL THREAD CLAMP SIZE

ZBI 113	1/2" x 20 NF	1 - 13 mm
ZBI 116	1/2" x 20 NF	2.5 - 16 mm



QUICK-ACTION DRILL CHUCK

ORD. NO	. INTERNAL THREAD	CLAMP SIZE
ZSI 113	1/2" x 20 NF	1 - 13 mm
ZSI 116	1/2" x 20 NF	3 - 16 mm



1. Connect taper drift to drill chuck.



2. Place drill chuck in MT arbor.



3. Ready for use with twist drill.

For magnetic core drilling machines with Morse taper MK 2 or MK 3. **ProfiPLUS** MAB 485 / 485 SB

MABasic 200 MABasic 400

AkkuMAB 3000

MAB 485

MAB 525 / 525 SB MAB 825 / 845 SB

MAB 1300

ProfiSTART MAB 455 / 455 SB

MAB 855

ProfiBASIC MABasic 450 ProfiSPEZIAL AirMAB 5000



TAPER DRIFT FOR DRILL CHUCK

ORDER NO.

ZKD 216 DIN 238 - MK 2/B16 ZKD 316 DIN 238 - MK 3/B16



GEAR RIM DRILL CHUCK

ORD. NO. INTERNAL THREAD CLAMP SIZE

ZBK 113 DIN 238-B16 1 - 13 mm ZBK 116 DIN 238-B16 2.5 - 16 mm



QUICK-ACTION DRILL CHUCK

ORD. NO.	INTERNAL THREAD	CLAMP SIZE

ZSB 113 DIN 238-B16 1 - 13 mm ZSB 116 DIN 238-B16 3 - 16 mm



KEY FOR GEAR RIM DRILL CHUCK

ORDER NO.

ZEZ 113 ZEZ 116



DRILL DRIFT DIN 228

ORD. NO.	SIZE	DIN STANDARD
ZAS 002	MK 2	DIN 228
ZAS 003	MK 3	DIN 228



CHIP PROTECTION ORD. NO. MACHINE

ZSS 050 MAB 100 - MAB 525 ZSS 500 MAB 825 – MAB 855

SAFETY CHAIN

ORDER NO.

ZSK 001



PUMP BOTTLE ORDER NO.

ZKP 100

Tool holders and adapters

For BDS core drills with Weldon shanks - suitable for adaptation to external systems.

Tool holders for BDS core drills with Weldon arbor. Three systems are available; they allow for a friction-locked, comfortable and secure connection between the core drill and the magnetic core drilling machine.

Tool holder for BDS core drills with Weldon shanks 19 mm $(^3/_4")$

Tool holder for BDS core drills with Weldon shanks 19 mm ($^3/_4$ ") and 32 mm ($^1/_4$ ")

Tool holder for BDS core drills with 19 mm Weldon shanks ($^3/_4$ ") and 32 mm ($^1/_4$ ")





ORDER NO. SPINDLE HOLDER

ZSS 200	MK 2	
ZSS 300	MK 3	
With automatic internal lubrication for core		
with Weldo	shank 19 mm ($^3/_4$ ").	
With hose	and quick acting coupling. Quick tool	



INDUSTRIAL ARBOR WITH MANUAL INTERNAL LUBRICATION

ORDER NO. SPINDLE HOLDER

ZIA 219-M	MK 2
ZIA 319-M	MK 3
ZIA 419-M	MK 4
For core drill	Is with 19 mm Weldon shank $\binom{3}{4}$ ")
ZIA 332-M	MK 3
ZIA 432-M	MK 4
For core drill	Is with 32 mm Weldon shank ($1^1/4^{"}$)



INDUSTRIAL ARBOR WITH AUTOMATIC INTERNAL LUBRICATION

ODDED NO. COINDLE HOLDED

UKDEK NU.	SPINULE HULDER
ZIA 219-KN	MK 2
ZIA 319-KN	MK 3
ZIA 419-KN	MK 4
For core drills	s with 19 mm Weldon shank $\binom{3}{4}$ ")
ZIA 332-KN	MK 3
ZIA 432-KN	MK 4
For core drills	s with 32 mm Weldon shank ($1^1/4^{"}$)
With hose an	d quick acting coupling.



REDUCING BUSH DIN 2185

change without any chuck key.

ORDER NO	. OUTSIDE	INSIDE	
ZRH 210	MK 2	MK 1	



EXTENSIO	N BUSH DIN	2178	
ORDER N	O. OUTSIDE	INSIDE	
ZVH 220	MK 2	MK 2	
ZVH 230	MK 2	MK 3	
ZVH 320	MK 3	MK 2	
ZVH 330	MK 3	MK 3	

Adapters for BDS core drills. With the appropriate adapter, BDS core drills with Weldon shanks are compatible with standard machines or tool holder systems on the market.

